

Release Note

Name	Version	Supported OS	Supported Products	Changes
Mac Touch Panel Driver	Ver. 2.8.2.0	macOS 10.15 / 11	PN-L851H/PN-L751H/PN-L651H PN-L805H/PN-L705H/PN-L803CA/PN-L803C/PN-L703WA PN-L703W/PN-L703A/PN-L703B PN-L603WA/PN-L603W/PN-L603A/PN-L603B/PN-L501C/PN-L401C PN-85TH1/PN-75TH1/PN-65TH1 PN-80TH5/PN-70TH5/PN-80TC3A/PN-80TC3/PN-70TW3A/PN-70TW3/PN-70TA3/PN-70TB3 PN-60TW3A/PN-60TW3/PN-60TA3/PN-60TB3/PN-50TC1/PN-40TC1 PN-ZL01A/PN-ZL02A/PN-ZL03A/PN-ZL06/PN-ZL01/PN-ZL02/PN-ZL03	<Changes of Ver. 2.8.2.0> - Added supports for macs with Apple silicon * You will need to install Rosetta. When prompted to install Rosetta, follow the dialog to install Rosetta * Multi-screen function is not supported - Other functional improvements